## **CORE POLICY**



## **General Policy**

All core returns must be,

- like for like, no mixed models
- drained of all fluids (\$50 Charge)
- be returned in the original packaging
- Part Disassembled

- No junkyard cores (core must have been removed from vehicle)
- No fire damage
- No Excessive Rust or Water Damage

Returned cores that fail to follow the above conditions will be disallowed and scrapped or returned at customer's expense. BD Diesel reserves the right to adjudicate cores as it sees fit and may deviate from its policy. Freight and removal damage are not covered.

BD FUEL INJECTION CORE ACCEPTANCE POLICY				
Model	Deduction	No Credit		
P7100 Injection Pump	<ul> <li>AFC Housing Damaged (25% Deduction)</li> <li>Governor Housing Damaged Front or Back (25% Deduction)</li> </ul>	<ul><li>Contaminated/Bio Diesel</li><li>Damaged Camshaft on 911/913 pumps.</li><li>Main Body Damaged</li></ul>		
Bosch VE Pump	<ul> <li>AFC Housing Damaged (25% Deduction)</li> <li>Cold Advanced Housing Damaged (50% Deduction)</li> <li>Governor housing damaged front or back (25% deduction)</li> <li>Main Body Damaged (50% Deduction)</li> </ul>	Contaminated/Bio Diesel     Seized Head (Does not turn)		
CP3		<ul> <li>Contaminated/Bio Diesel</li> <li>Seized (Does not turn)</li> <li>Catastrophic Shaft Failure (Frost Plugs Damaged or Missing)</li> <li>Front Cover Damaged</li> </ul>		
VP44	Damaged Electronics (50% Deduction)	Contaminated/Bio Diesel     Seized Head (Does not turn)		
Common Rail Injectors	<ul> <li>Solenoid melted or destroyed, stretched terminals (25% Deduction)</li> <li>5.9/6.7 Broken Solenoid Terminal Divider (No Deduction)</li> </ul>	Contaminated/Bio Diesel     Damaged Body		
Mechanical Injectors		Contaminated/Bio Diesel     Damaged Body		

BD TURBOCHARGER CORE ACCEPTANCE POLICY					
Turbo Model/ Application	Deduction	No Credit			
Cummins ISX VGT Air or Electronic Actuated	<ul> <li>Damaged Electronics (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Turbine Wheel Separation (50% Deduction)</li> </ul>	<ul><li> Knock Off Models (Not Genuine)</li><li> Part Disassembled</li></ul>			
Caterpillar (Ball Bearing) Models		<ul><li>Knock Off Models (Not Genuine)</li><li>Wheel Separation</li></ul>			
Caterpillar (Standard Turbocharger)		<ul><li>Knock Off Models (Not Genuine)</li><li>Turbo with 3 support Webs</li></ul>			

BDDIESEL.COM

704604-9007, 704604- 9011)		
Detroit Diesel VGT	Damaged Electronics (50% Deduction)	Knock Off Models (Not Genuine)     Wheel Separation
Ford 6.4 Powerstroke	Missing Parts or Actuators (50% Deduction)	Knock Off Models (Not Genuine)     Part disassembled     Wheel Separation
Ford 6.7 Powerstroke	Missing Parts or Actuators (50% Deduction)	Wheel Separation
Dodge Cummins 6.7 HE351VG/HE300VG	Missing Parts or Actuators (50% Deduction)	Knock Off Models (Not Genuine)
Standard Turbochargers (All Models, Non VGT)	<ul> <li>Damaged Electronics (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Missing Parts or Actuators (50% Deduction)</li> </ul>	Knock Off Models (Not Genuine)     Wheel Separation

<b>BD TRANSMISSION/TORQUE CONVERTOR CORE ACCEPTANCE POLICY</b>				
Model	Deduction	No Credit		
Transmissions	<ul> <li>Cracked Overdrive housings (\$100 Deduction)</li> <li>68rfe Cracked Case (25% Deduction)</li> <li>Part disassembled (50% Deduction)</li> <li>Missing Transmission Shipping Crate (\$200 Deduction)</li> <li>Missing TC/Transmission bracket (\$50 Deduction)</li> </ul>	Cracked Case (Except 68rfe)		
Torque Convertors	Hub and Impeller damaged. (50% Deduction)	<ul><li>Excessive corrosion</li><li>Part disassembled</li></ul>		
Valve Bodies	Missing electronics (25% Deduction)	<ul><li>Excessive corrosion</li><li>Part disassembled</li></ul>		
GENERAL CORE ACCEPTANCE POLICY				
Model	Deduction	No Credit		
EGR Cooler		Brackets broken		