



8.75" Billet Overflow Tank

#77109 / #BLK77109

Top edge of mounting bracket should not be less than 2in. from top of overflow tank.

It is recommended to locate the mounting bracket as close to the center of tank as possible. Installing the bracket near the top may distort the shape of the tank, resulting in a difficult or impossible to remove cap.

