POLARIS XPEDITION



Kit Components:		
Item #	Qty.	Description
1	1	Plow Mount
2	1	Frame Mount
3	1	Hardware Kit HK-417
3.1	4	3/8"-16 X 1.00" Hex Bolt Flange Serrated GR5
3.2	4	3/8"-16 Hex Nut Flange Nylock GR5







©2023 Copyright Kappers Fabricating, Inc. All rights reserved

INSTALLATION INSTRUCTIONS

Note: Make sure all hardware needed to complete this mount is in the package. Thoroughly read through and understand the instructions before installing.

- 1. Locate the lower tow bracket bolts (A) shown in **Figure 1**, and remove them from the machine. This hardware will be reused.
- 2. Safely jack up the machine to take the pressure off of the A-Arms. Remove the rear bolts (B) from the lower A-Arms as shown in **Figure 1**. This hardware will be reused.
- Place the Frame Mount (2) on the machine as shown in Figure
 2 and loosely secure the front with Bolts (A), removed in Step 1.
- Reinstall bolts (B), removed in Step 2, through the Frame Mount
 (2) and through the original location on the lower A-Arm as shown in Figure 2.
- 5. Tighten hardware evenly according to manufactures specification
- Use hardware (3.1 and 3.2) to attach Plow Mount (1) onto the Frame Mount (2) as shown in Figure 3 and the Exploded Diagram on the front page.

Note: Plow Mount (1) is designed to be removed in the off season so you don't lose ground clearence.

7. Tighten Hardware (3.1 and 3.2) evenly.





