



Counting up from
the bottom,
remove fins 4 & 5
from both sides



IF required, trim off the lower mounts for additional clearance, shown in RED

NOTE: Make sure motor assembly is NOT modified.

Motor is in the center of the shutter assembly (as marked in green)



Reinstall the shutter assembly, using the factory three mounting locations at the top of the grille. Ensure connector is reconnected.

Fit should be tight, however it's recommended to use zip ties to secure bottom of assembly.



Ensure clearance of the grille supports through the shutter assembly

